

SHORELINE RESTORATION WITH FRONTIER PONDS, INC.

BEFORE:

This property has a pond on either side of this road that runs past them to the back of the property. The shoreline of both ponds has been eroding, endangering the road's stability. Frontier Ponds was brought in to secure the shoreline on both sides of the road to save this single pathway to the back of the property.



DURING:

Frontier Ponds brought in large boulders and gravel to secure the shoreline. Boulders were strategically placed in the pond, the area was backfilled with gravel and more boulders were placed, ensuring that the erosion will stop.



SHORELINE RESTORATION WITH FRONTIER PONDS, INC.



AFTER:

The end result is a beautiful shoreline on either side of the roadway which is now stable and there is no danger of collapse.

